



North Florida Headquarters
 3562 NW 97th Boulevard, Gainesville, Florida 32606
 (352) 727-7696 Office - (352) 727-7697 Fax
 northflorida@lakeandwetland.com

SERVICE & INSPECTION REPORT

Customer: Longleaf Master Account #: 1008 Date: 4/4/19
 Technician: Jeff + Veronica Weather Conditions: 78°F Sunny

LAKE MANAGEMENT

- ALGAE CONTROL
- GRASSES & EMERGENTS
- SUBMERSED AQUATICS
- FLOATING PLANTS
- INSPECTION
- DEBRIS

Lake(s) #: 2, 5, 11, 13
 Lake(s) #: 1, 5, 13
 Lake(s) #: _____
 Lake(s) #: _____
 Lake(s) #: _____
 Lake(s) #: 11, 13

Water Test Results (Combined Average)

Temperature	<u>30</u> °F	<input type="checkbox"/> HIGH	<input checked="" type="checkbox"/> AVERAGE	<input type="checkbox"/> LOW
Dissolved Oxygen	_____ ppm	<input type="checkbox"/> HIGH	<input type="checkbox"/> AVERAGE	<input type="checkbox"/> LOW
pH reading	_____	<input type="checkbox"/> ACID	<input type="checkbox"/> NEUTRAL	<input type="checkbox"/> BASE
Water Clarity	<u>1-2 ft</u>	<input type="checkbox"/> GOOD	<input checked="" type="checkbox"/> FAIR	<input type="checkbox"/> POOR
Water Level	<u>AVG</u>	<input type="checkbox"/> HIGH	<input checked="" type="checkbox"/> AVERAGE	<input type="checkbox"/> LOW

FOUNTAIN / AERATION SYSTEM SERVICE

- | | | |
|---|---|--|
| <input type="checkbox"/> DISPLAY HEADS | <input type="checkbox"/> LIGHT FIXTURES | <input type="checkbox"/> INSPECTION |
| <input type="checkbox"/> FLOATS | <input type="checkbox"/> COMPRESSORS | <input type="checkbox"/> PARTS INSTALLED |
| <input type="checkbox"/> INTAKE SCREENS | <input type="checkbox"/> DIFFUSERS | (noted below) |

UPLAND / LITTORAL / WETLAND MANAGEMENT

- | | | |
|--|--|-------------------------------------|
| <input type="checkbox"/> INVASIVE / EXOTIC SPECIES | <input type="checkbox"/> HERBICIDE TREATMENT | <input type="checkbox"/> INSPECTION |
| <input type="checkbox"/> GRASSES | <input type="checkbox"/> MANUAL REMOVAL | |
| <input type="checkbox"/> VINES | <input type="checkbox"/> DEBRIS REMOVAL | |

MOSQUITO / MIDGE LARVAE CONTROL

- INSECTICIDE TREATMENT Lake(s) #: _____
 INSPECTION

Comments: Used algaeicide on lakes # 1, 5, 11, 13 to help control algae. Sprayed herbicide to control invasive plant species such as primrose, pennywort, alligatorweed, cattail, slender spike rush, and grasses. Handpulled saltbush and primrose. Removed trash and debris on lakes (#11, #13) total 1 bag.

FISH & WILDLIFE OBSERVATIONS

- | | | | | | | |
|---|--------------------------------|-------------------------------------|-------------------------------------|---|--|---|
| FISH: <input type="checkbox"/> Bass | <input type="checkbox"/> Bream | <input type="checkbox"/> Catfish | <input type="checkbox"/> Grass carp | <input type="checkbox"/> Tilapia | <input checked="" type="checkbox"/> Mosquitofish | <input type="checkbox"/> Shad |
| BIRDS: <input checked="" type="checkbox"/> Raptor | <input type="checkbox"/> Duck | <input type="checkbox"/> Wood Stork | <input type="checkbox"/> Shorebird | <input checked="" type="checkbox"/> Wading bird | <input checked="" type="checkbox"/> Songbird | <input checked="" type="checkbox"/> Vulture |
| REPTILES: <input checked="" type="checkbox"/> Alligator | <input type="checkbox"/> Snake | <input type="checkbox"/> Turtle | <input type="checkbox"/> Tortoise | <input checked="" type="checkbox"/> Lizard | <input checked="" type="checkbox"/> AMPHIBIANS | <input checked="" type="checkbox"/> INSECTS |

INVASIVE / EXOTIC PLANTS OBSERVED

- | | | | | | | | |
|-----------------------------------|---|---|---|---|---|---|--|
| <input type="checkbox"/> Hydrilla | <input checked="" type="checkbox"/> Alligatorweed | <input checked="" type="checkbox"/> Pennywort | <input type="checkbox"/> Watermeal | <input checked="" type="checkbox"/> Sedge | <input type="checkbox"/> Limnophila | <input type="checkbox"/> Air potato | <input checked="" type="checkbox"/> Torpedograss |
| <input type="checkbox"/> Azolla | <input type="checkbox"/> Salvinia | <input type="checkbox"/> Lantana | <input checked="" type="checkbox"/> Slender spikerush | <input type="checkbox"/> Cogongrass | <input type="checkbox"/> Water hyacinth | <input checked="" type="checkbox"/> Cattail | <input checked="" type="checkbox"/> Primrose |

NATIVE PLANTS OBSERVED

- | | | | | | | | |
|----------------------------------|--|---|-------------------------------------|-------------------------------------|--------------------------------------|------------------------------------|--|
| <input type="checkbox"/> Cypress | <input checked="" type="checkbox"/> Pickerelweed | <input type="checkbox"/> Waterlily | <input type="checkbox"/> Mangrove | <input type="checkbox"/> Pond Apple | <input type="checkbox"/> Bulrush | <input type="checkbox"/> Red Maple | <input type="checkbox"/> Arrowhead |
| <input type="checkbox"/> Thalia | <input type="checkbox"/> Golden Canna | <input checked="" type="checkbox"/> Spikerush | <input type="checkbox"/> Buttonbush | <input type="checkbox"/> Eelgrass | <input type="checkbox"/> Cordgrass | <input type="checkbox"/> Oak | <input type="checkbox"/> Spatterdock |
| <input type="checkbox"/> Ferns | <input type="checkbox"/> Baby tears | <input type="checkbox"/> Naiad | <input type="checkbox"/> Chara | <input type="checkbox"/> Duckweed | <input type="checkbox"/> Bladderwort | <input type="checkbox"/> Pondweed | <input checked="" type="checkbox"/> Bacopa |

Other species noted / comments: _____