



North Florida Headquarters
 3562 NW 97th Boulevard, Gainesville, Florida 32606
 (352) 727-7696 Office - (352) 727-7697 Fax
 northflorida@lakeandwetland.com

SERVICE & INSPECTION REPORT

Customer: Longleaf Master HOA Account #: 1088 Date: 6-27-19
 Technician: JEFF Weather Conditions: 90°, cloudy

LAKE MANAGEMENT

- | | | |
|---|------------|-----------------------|
| <input type="checkbox"/> ALGAE CONTROL | Lake(s) #: | _____ |
| <input checked="" type="checkbox"/> GRASSES & EMERGENTS | Lake(s) #: | <u>5, 9-12, 16-18</u> |
| <input type="checkbox"/> SUBMERSED AQUATICS | Lake(s) #: | _____ |
| <input type="checkbox"/> FLOATING PLANTS | Lake(s) #: | _____ |
| <input type="checkbox"/> INSPECTION | Lake(s) #: | _____ |
| <input checked="" type="checkbox"/> DEBRIS | Lake(s) #: | <u>5, 9-12, 16-18</u> |

Water Test Results (Combined Average)

| | | | | |
|------------------|--------------|-------------------------------|---|-------------------------------|
| Temperature | <u>74</u> °F | <input type="checkbox"/> HIGH | <input checked="" type="checkbox"/> AVERAGE | <input type="checkbox"/> LOW |
| Dissolved Oxygen | <u>7</u> ppm | <input type="checkbox"/> HIGH | <input checked="" type="checkbox"/> AVERAGE | <input type="checkbox"/> LOW |
| pH reading | <u>7.8</u> | <input type="checkbox"/> ACID | <input checked="" type="checkbox"/> NEUTRAL | <input type="checkbox"/> BASE |
| Water Clarity | <u>0-4ft</u> | <input type="checkbox"/> GOOD | <input checked="" type="checkbox"/> FAIR | <input type="checkbox"/> POOR |
| Water Level | <u>4.5</u> | <input type="checkbox"/> HIGH | <input checked="" type="checkbox"/> AVERAGE | <input type="checkbox"/> LOW |

FOUNTAIN / AERATION SYSTEM SERVICE

- | | | | |
|---|---|-------------|--|
| <input type="checkbox"/> DISPLAY HEADS | Unit(s) #: | <u>1, 2</u> | <input checked="" type="checkbox"/> INSPECTION |
| <input type="checkbox"/> FLOATS | <input type="checkbox"/> LIGHT FIXTURES | | <input type="checkbox"/> PARTS INSTALLED |
| <input type="checkbox"/> INTAKE SCREENS | <input type="checkbox"/> COMPRESSORS | | (noted below) |
| | <input type="checkbox"/> DIFFUSERS | | |

UPLAND / LITTORAL / WETLAND MANAGEMENT Area(s) #:

- | | | |
|--|--|-------------------------------------|
| <input type="checkbox"/> INVASIVE / EXOTIC SPECIES | <input type="checkbox"/> HERBICIDE TREATMENT | <input type="checkbox"/> INSPECTION |
| <input type="checkbox"/> GRASSES | <input type="checkbox"/> MANUAL REMOVAL | |
| <input type="checkbox"/> VINES | <input type="checkbox"/> DEBRIS REMOVAL | |

MOSQUITO / MIDGE LARVAE CONTROL

- | | | |
|--|------------|-------|
| <input type="checkbox"/> INSECTICIDE TREATMENT | Lake(s) #: | _____ |
| <input type="checkbox"/> INSPECTION | | |

Comments: Used herbicide to treat primrose, cattail, alligatorweed, pennywort and other weedy emergents around the perimeters of above listed lakes. Also removed trash from these lakes. Visually inspected both fountains on lakes 1 & 2 and both are functioning properly.

FISH & WILDLIFE OBSERVATIONS

- | | | | | | | | |
|-----------|------------------------------------|--------------------------------|-------------------------------------|-------------------------------------|---|--|---|
| FISH: | <input type="checkbox"/> Bass | <input type="checkbox"/> Bream | <input type="checkbox"/> Catfish | <input type="checkbox"/> Grass carp | <input type="checkbox"/> Tilapia | <input type="checkbox"/> Mosquitofish | <input type="checkbox"/> Shad |
| BIRDS: | <input type="checkbox"/> Raptor | <input type="checkbox"/> Duck | <input type="checkbox"/> Wood Stork | <input type="checkbox"/> Shorebird | <input checked="" type="checkbox"/> Wading bird | <input checked="" type="checkbox"/> Songbird | <input type="checkbox"/> Vulture |
| REPTILES: | <input type="checkbox"/> Alligator | <input type="checkbox"/> Snake | <input type="checkbox"/> Turtle | <input type="checkbox"/> Tortoise | <input checked="" type="checkbox"/> Lizard | <input checked="" type="checkbox"/> AMPHIBIANS | <input checked="" type="checkbox"/> INSECTS |

INVASIVE / EXOTIC PLANTS OBSERVED

- | | | | | | | | |
|-----------------------------------|---|---|--|---|---|---|--|
| <input type="checkbox"/> Hydrilla | <input checked="" type="checkbox"/> Alligatorweed | <input checked="" type="checkbox"/> Pennywort | <input type="checkbox"/> Watermeal | <input checked="" type="checkbox"/> Sedge | <input type="checkbox"/> Limnophila | <input type="checkbox"/> Air potato | <input type="checkbox"/> Torpedograss |
| <input type="checkbox"/> Azolla | <input type="checkbox"/> Salvinia | <input type="checkbox"/> Lantana | <input type="checkbox"/> Slender spikerush | <input type="checkbox"/> Cogongrass | <input type="checkbox"/> Water hyacinth | <input checked="" type="checkbox"/> Cattail | <input checked="" type="checkbox"/> Primrose |

NATIVE PLANTS OBSERVED

- | | | | | | | | |
|----------------------------------|---------------------------------------|------------------------------------|-------------------------------------|-------------------------------------|--------------------------------------|------------------------------------|--|
| <input type="checkbox"/> Cypress | <input type="checkbox"/> Pickerelweed | <input type="checkbox"/> Waterlily | <input type="checkbox"/> Mangrove | <input type="checkbox"/> Pond Apple | <input type="checkbox"/> Bulrush | <input type="checkbox"/> Red Maple | <input type="checkbox"/> Arrowhead |
| <input type="checkbox"/> Thalia | <input type="checkbox"/> Golden Canna | <input type="checkbox"/> Spikerush | <input type="checkbox"/> Buttonbush | <input type="checkbox"/> Eelgrass | <input type="checkbox"/> Cordgrass | <input type="checkbox"/> Oak | <input type="checkbox"/> Spatterdock |
| <input type="checkbox"/> Ferns | <input type="checkbox"/> Baby tears | <input type="checkbox"/> Naiad | <input type="checkbox"/> Chara | <input type="checkbox"/> Duckweed | <input type="checkbox"/> Bladderwort | <input type="checkbox"/> Pondweed | <input checked="" type="checkbox"/> Bacopa |

Other species noted / comments: _____