



Lake & Wetland

MANAGEMENT

North Florida Headquarters
3562 NW 97th Boulevard, Gainesville, Florida 32606
(352) 727-7696 Office - (352) 727-7697 Fax
northflorida@lakeandwetland.com

SERVICE & INSPECTION REPORT

Customer: Longleaf Moske HOA Account #: 1088 Date: 8-8-19
Technician: Jeff Weather Conditions: 86, mostly cloudy

LAKE MANAGEMENT

- ALGAE CONTROL
- GRASSES & EMERGENTS
- SUBMERSED AQUATICS
- FLOATING PLANTS
- INSPECTION
- DEBRIS

Lake(s) #: 16
 Lake(s) #: 1, 2, 13-17
 Lake(s) #: _____
 Lake(s) #: _____
 Lake(s) #: _____
 Lake(s) #: 1, 2, 13-17

Water Test Results (Combined Average)

Temperature 76 °F
 Dissolved Oxygen 7 ppm
 pH reading 7.8
 Water Clarity 0-4ft
 Water Level AVG

- | | | |
|-------------------------------|---|-------------------------------|
| <input type="checkbox"/> HIGH | <input checked="" type="checkbox"/> AVERAGE | <input type="checkbox"/> LOW |
| <input type="checkbox"/> HIGH | <input checked="" type="checkbox"/> AVERAGE | <input type="checkbox"/> LOW |
| <input type="checkbox"/> ACID | <input checked="" type="checkbox"/> NEUTRAL | <input type="checkbox"/> BASE |
| <input type="checkbox"/> GOOD | <input checked="" type="checkbox"/> FAIR | <input type="checkbox"/> POOR |
| <input type="checkbox"/> HIGH | <input checked="" type="checkbox"/> AVERAGE | <input type="checkbox"/> LOW |

FOUNTAIN / AERATION SYSTEM SERVICE

- | | | |
|---|---|--|
| <input type="checkbox"/> DISPLAY HEADS | <input type="checkbox"/> LIGHT FIXTURES | <input type="checkbox"/> INSPECTION |
| <input type="checkbox"/> FLOATS | <input type="checkbox"/> COMPRESSORS | <input type="checkbox"/> PARTS INSTALLED |
| <input type="checkbox"/> INTAKE SCREENS | <input type="checkbox"/> DIFFUSERS | (noted below) |

Unit(s) #: 2-2

UPLAND / LITTORAL / WETLAND MANAGEMENT

- | | | |
|--|--|-------------------------------------|
| <input type="checkbox"/> INVASIVE / EXOTIC SPECIES | <input type="checkbox"/> HERBICIDE TREATMENT | <input type="checkbox"/> INSPECTION |
| <input type="checkbox"/> GRASSES | <input type="checkbox"/> MANUAL REMOVAL | |
| <input type="checkbox"/> VINES | <input type="checkbox"/> DEBRIS REMOVAL | |

MOSQUITO / MIDGE LARVAE CONTROL

- | | |
|--|------------------|
| <input type="checkbox"/> INSECTICIDE TREATMENT | Lake(s) #: _____ |
| <input type="checkbox"/> INSPECTION | |

Comments: Used herbicide to treat sedge, pennywort, cattail, alligatorweed, torpedograss, primrose and other weedy emergents around the perimeter of above listed lakes. Also treated algae on lake 16 with algaeicide. Removed trash during visit. Visually inspected both fountains - functioning properly.

FISH & WILDLIFE OBSERVATIONS

- | | | | | | | |
|--|--------------------------------|-------------------------------------|-------------------------------------|---|--|---|
| FISH: <input type="checkbox"/> Bass | <input type="checkbox"/> Bream | <input type="checkbox"/> Catfish | <input type="checkbox"/> Grass carp | <input type="checkbox"/> Tilapia | <input type="checkbox"/> Mosquitofish | <input type="checkbox"/> Shad |
| BIRDS: <input type="checkbox"/> Raptor | <input type="checkbox"/> Duck | <input type="checkbox"/> Wood Stork | <input type="checkbox"/> Shorebird | <input checked="" type="checkbox"/> Wading bird | <input type="checkbox"/> Songbird | <input type="checkbox"/> Vulture |
| REPTILES: <input type="checkbox"/> Alligator | <input type="checkbox"/> Snake | <input type="checkbox"/> Turtle | <input type="checkbox"/> Tortoise | <input checked="" type="checkbox"/> Lizard | <input checked="" type="checkbox"/> AMPHIBIANS | <input checked="" type="checkbox"/> INSECTS |

INVASIVE / EXOTIC PLANTS OBSERVED

- | | | | | | | | |
|-----------------------------------|---|---|---|---|---|---|--|
| <input type="checkbox"/> Hydrilla | <input checked="" type="checkbox"/> Alligatorweed | <input checked="" type="checkbox"/> Pennywort | <input type="checkbox"/> Watermeal | <input checked="" type="checkbox"/> Sedge | <input type="checkbox"/> Limnophila | <input type="checkbox"/> Air potato | <input checked="" type="checkbox"/> Torpedograss |
| <input type="checkbox"/> Azolla | <input type="checkbox"/> Salvinia | <input type="checkbox"/> Lantana | <input checked="" type="checkbox"/> Slender spikerush | <input type="checkbox"/> Cogongrass | <input type="checkbox"/> Water hyacinth | <input checked="" type="checkbox"/> Cattail | <input checked="" type="checkbox"/> Primrose |

NATIVE PLANTS OBSERVED

- | | | | | | | | |
|----------------------------------|---------------------------------------|------------------------------------|-------------------------------------|-------------------------------------|--------------------------------------|------------------------------------|--|
| <input type="checkbox"/> Cypress | <input type="checkbox"/> Pickerelweed | <input type="checkbox"/> Waterlily | <input type="checkbox"/> Mangrove | <input type="checkbox"/> Pond Apple | <input type="checkbox"/> Bulrush | <input type="checkbox"/> Red Maple | <input type="checkbox"/> Arrowhead |
| <input type="checkbox"/> Thalia | <input type="checkbox"/> Golden Canna | <input type="checkbox"/> Spikerush | <input type="checkbox"/> Buttonbush | <input type="checkbox"/> Eelgrass | <input type="checkbox"/> Cordgrass | <input type="checkbox"/> Oak | <input type="checkbox"/> Spatterdock |
| <input type="checkbox"/> Ferns | <input type="checkbox"/> Baby tears | <input type="checkbox"/> Naiad | <input type="checkbox"/> Chara | <input type="checkbox"/> Duckweed | <input type="checkbox"/> Bladderwort | <input type="checkbox"/> Pondweed | <input checked="" type="checkbox"/> Bacopa |

Other species noted / comments: _____