



North Florida Headquarters
 3562 NW 97th Boulevard, Gainesville, Florida 32606
 (352) 727-7696 Office - (352) 727-7697 Fax
 northflorida@lakeandwetland.com

SERVICE & INSPECTION REPORT

Customer: Longleaf Account #: 1088 Date: 9-19-19
 Technician: Jeff Weather Conditions: 85°, Cloudy

LAKE MANAGEMENT

<input checked="" type="checkbox"/> ALGAE CONTROL	Lake(s) #:	<u>10, 11, 14, 16</u>
<input checked="" type="checkbox"/> GRASSES & EMERGENTS	Lake(s) #:	<u>1, 2, 4, 14, 15, 16</u>
<input type="checkbox"/> SUBMERSED AQUATICS	Lake(s) #:	
<input type="checkbox"/> FLOATING PLANTS	Lake(s) #:	
<input type="checkbox"/> INSPECTION	Lake(s) #:	
<input checked="" type="checkbox"/> DEBRIS	Lake(s) #:	<u>1-2, 4-5, 14-16, 11, 10</u>

Water Test Results (Combined Average)

Temperature	<u>78</u> °F	<input type="checkbox"/> HIGH	<input checked="" type="checkbox"/> AVERAGE	<input type="checkbox"/> LOW
Dissolved Oxygen	<u>7</u> ppm	<input type="checkbox"/> HIGH	<input checked="" type="checkbox"/> AVERAGE	<input type="checkbox"/> LOW
pH reading	<u>7.8</u>	<input type="checkbox"/> ACID	<input checked="" type="checkbox"/> NEUTRAL	<input type="checkbox"/> BASE
Water Clarity	<u>0-6ft</u>	<input checked="" type="checkbox"/> GOOD	<input type="checkbox"/> FAIR	<input type="checkbox"/> POOR
Water Level	<u>AVG</u>	<input type="checkbox"/> HIGH	<input checked="" type="checkbox"/> AVERAGE	<input type="checkbox"/> LOW

FOUNTAIN / AERATION SYSTEM SERVICE

<input type="checkbox"/> DISPLAY HEADS	Unit(s) #:	<u>1, 2 - waiting for parts</u>	<input type="checkbox"/> INSPECTION
<input type="checkbox"/> FLOATS	<input type="checkbox"/> LIGHT FIXTURES		<input type="checkbox"/> PARTS INSTALLED
<input type="checkbox"/> INTAKE SCREENS	<input type="checkbox"/> COMPRESSORS		(noted below)
	<input type="checkbox"/> DIFFUSERS		

UPLAND / LITTORAL / WETLAND MANAGEMENT Area(s) #:

<input type="checkbox"/> INVASIVE / EXOTIC SPECIES	<input type="checkbox"/> HERBICIDE TREATMENT	<input type="checkbox"/> INSPECTION
<input type="checkbox"/> GRASSES	<input type="checkbox"/> MANUAL REMOVAL	
<input type="checkbox"/> VINES	<input type="checkbox"/> DEBRIS REMOVAL	

MOSQUITO / MIDGE LARVAE CONTROL Lake(s) #:

<input type="checkbox"/> INSECTICIDE TREATMENT	<input type="checkbox"/> INSPECTION
--	-------------------------------------

Comments: used herbicide to treat pennywort, alligatorweed, sedge, torpedograss and other weedy invasive emergents around the perimeter of listed lakes. Also treated algae on edge of listed lakes with algicide. Removed trash. Inspected fountains #1 is working properly + waiting for parts to replace on #2.

FISH & WILDLIFE OBSERVATIONS

- | | | | | | | |
|--|--------------------------------|--|-------------------------------------|--|--|---|
| FISH: <input type="checkbox"/> Bass | <input type="checkbox"/> Bream | <input type="checkbox"/> Catfish | <input type="checkbox"/> Grass carp | <input type="checkbox"/> Tilapia | <input type="checkbox"/> Mosquitofish | <input type="checkbox"/> Shad |
| BIRDS: <input type="checkbox"/> Raptor | <input type="checkbox"/> Duck | <input type="checkbox"/> Wood Stork | <input type="checkbox"/> Shorebird | <input type="checkbox"/> Wading bird | <input type="checkbox"/> Songbird | <input type="checkbox"/> Vulture |
| REPTILES: <input type="checkbox"/> Alligator | <input type="checkbox"/> Snake | <input checked="" type="checkbox"/> Turtle | <input type="checkbox"/> Tortoise | <input checked="" type="checkbox"/> Lizard | <input checked="" type="checkbox"/> AMPHIBIANS | <input checked="" type="checkbox"/> INSECTS |

INVASIVE / EXOTIC PLANTS OBSERVED

- | | | | | | | | |
|-----------------------------------|---|------------------------------------|--|---|---|-------------------------------------|--|
| <input type="checkbox"/> Hydrilla | <input checked="" type="checkbox"/> Alligatorweed | <input type="checkbox"/> Pennywort | <input type="checkbox"/> Watermeal | <input checked="" type="checkbox"/> Sedge | <input type="checkbox"/> Limnophila | <input type="checkbox"/> Air potato | <input checked="" type="checkbox"/> Torpedograss |
| <input type="checkbox"/> Azolla | <input type="checkbox"/> Salvinia | <input type="checkbox"/> Lantana | <input type="checkbox"/> Slender spikerush | <input type="checkbox"/> Cogongrass | <input type="checkbox"/> Water hyacinth | <input type="checkbox"/> Cattail | <input checked="" type="checkbox"/> Primrose |

NATIVE PLANTS OBSERVED

- | | | | | | | | |
|----------------------------------|--|------------------------------------|-------------------------------------|-------------------------------------|--------------------------------------|------------------------------------|--|
| <input type="checkbox"/> Cypress | <input type="checkbox"/> Pickerelweed | <input type="checkbox"/> Waterlily | <input type="checkbox"/> Mangrove | <input type="checkbox"/> Pond Apple | <input type="checkbox"/> Bulrush | <input type="checkbox"/> Red Maple | <input type="checkbox"/> Arrowhead |
| <input type="checkbox"/> Thalia | <input type="checkbox"/> Golden Canna | <input type="checkbox"/> Spikerush | <input type="checkbox"/> Buttonbush | <input type="checkbox"/> Eelgrass | <input type="checkbox"/> Cordgrass | <input type="checkbox"/> Oak | <input type="checkbox"/> Spatterdock |
| <input type="checkbox"/> Ferns | <input checked="" type="checkbox"/> Baby tears | <input type="checkbox"/> Naiad | <input type="checkbox"/> Chara | <input type="checkbox"/> Duckweed | <input type="checkbox"/> Bladderwort | <input type="checkbox"/> Pondweed | <input checked="" type="checkbox"/> Bacopa |

Other species noted / comments: _____